

PROJECT ADDRESS	MUCKLESHOOT INDIAN TRIBE SUPPORTIVE HOUSING	Pricing cells	Email	support@aconengineering.com							
DUE DATE	38415 AUBURN ENUMCLAW RD SE 98092	Confirm pricing	PH #								
DATE ON PLANS	5/19/2025	Confirm inclusion in scope	Website	http://aconengineering.com/							
ADDENDUM UPDATE	11/27/2024										
REVISION #	Not Issued										
	0										
Total Basebid	\$15,000										
SR #	DESCRIPTION	QTY	UNIT	LABOR UNIT COST	MATERIAL UNIT COST	TOTAL LABOR	TOTAL MATERIAL	TOTAL COST	REMARKS		
	Exterior Wall Framing @ 1st Floor: (814 LF)										
1	2x6x16' #2 DFL pt	56	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Bottom Plate		
2	2x6x12' #2 DFL	674	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Wall Studs @ 16" O.C		
3	2x6x12' #2 DFL	604	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Extra Wall Studs (Openings, Corner & Intersections)		
4	2x6x16' #2 DFL	168	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Double Top Plate & Mid Span Blocking		
5	15/32" CDX Plywood 4x8	336	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Exterior Wall Sheathing		
6	10'x125' Tyvek	9	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Tyvek		
7	2"x165' Tyvek Tape	18	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Tyvek Tape		
	Unit Separation Wall Framing @ 1st Floor: (516 LF)										
8	2x4x16' #2 DFL pt	36	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Bottom Plate		
9	2x4x12' #2 DFL	563	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Wall Studs @ 16" O.C		
10	2x4x12' #2 DFL	160	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Extra Wall Studs (Openings, Corner & Intersections)		
11	2x4x16' #2 DFL	107	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Double Top Plate & Mid Span Blocking		
12	15/32" CDX Plywood 4x8	63	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Shear Wall Sheathing		
	Corridor Wall Framing @ 1st Floor: (658 LF)										
13	2x4x16' #2 DFL pt	10	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Bottom Plate		
14	3x4x16' #2 DFL pt	2	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Bottom Plate		
15	2x6x16' #2 DFL pt	37	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Bottom Plate		
16	2x4x12' #2 DFL	109	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Wall Studs @ 16" O.C		
17	2x4x12' #2 DFL	99	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Extra Wall Studs (Openings, Corner & Intersections)		
18	2x6x12' #2 DFL	662	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Wall Studs @ 16" O.C		
19	2x6x12' #2 DFL	365	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Extra Wall Studs (Openings, Corner & Intersections)		
20	2x4x16' #2 DFL	28	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Double Top Plate & Mid Span Blocking		
21	2x6x16' #2 DFL	109	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Double Top Plate & Mid Span Blocking		
22	15/32" CDX Plywood 4x8	131	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Shear Wall Sheathing		
	Interior Wall Framing @ 1st Floor: (1767 LF)										
23	2x4x16' #2 DFL pt	107	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Bottom Plate		
24	2x6x16' #2 DFL pt	16	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Bottom Plate		
25	2x4x12' #2 DFL	1326	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Wall Studs @ 16" O.C		
26	2x4x12' #2 DFL	948	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Extra Wall Studs (Openings, Corner & Intersections)		

SR #	DESCRIPTION	QTY	UNIT	LABOR UNIT COST	MATERIAL UNIT COST	TOTAL LABOR	TOTAL MATERIAL	TOTAL COST	REMARKS
27	2x6x12' #2 DFL	202	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Wall Studs @ 16" O.C
28	2x6x12' #2 DFL	91	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Extra Wall Studs (Openings, Corner & Intersections)
29	2x4x16' #2 DFL	319	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Double Top Plate & Mid Span Blocking
30	2x6x16' #2 DFL	46	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Double Top Plate & Mid Span Blocking
31	15/32" CDX Plywood 4x8	43	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Shear Wall Sheathing
	Exterior Headers/Beams @ 1st Floor:								
32	2x8x16' #2 HF	36	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Headers/Beams @ Openings
33	6x12x16' #1 DFL	3	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Headers/Beams @ Openings
34	3-1/2"x11-7/8" PSL (12' Long)	24	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
35	3-1/2"x11-7/8" PSL (10' Long)	20	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
36	3-1/2"x11-7/8" PSL (22' Long)	1	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
37	3-1/2"x11-7/8" PSL (12' Long)	1	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
38	3-1/2"x11-7/8" PSL (16' Long)	1	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
39	5-1/4"x11-7/8" PSL (22' Long)	1	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
40	5-1/2"x18" GL (8' Long)	3	EA	\$ -	\$ -	\$ -	\$ -	\$ -	GL Beam/Header
41	5-1/2"x18" GL (14' Long)	2	EA	\$ -	\$ -	\$ -	\$ -	\$ -	GL Beam/Header
	Interior Headers/Beams @ 1st Floor:								
42	2x8x16' #2 HF	59	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Headers/Beams @ Openings
43	3-1/2"x11-7/8" PSL (6' Long)	36	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
44	3-1/2"x11-7/8" PSL (8' Long)	8	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
45	3-1/2"x11-7/8" PSL (10' Long)	10	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
46	3-1/2"x11-7/8" PSL (12' Long)	4	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
47	3-1/2"x11-7/8" PSL (28' Long)	1	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
48	5-1/4"x11-7/8" PSL (22' Long)	1	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
49	5-1/4"x11-7/8" PSL (26' Long)	2	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
50	5-1/4"x11-7/8" PSL (10' Long)	6	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
51	5-1/4"x11-7/8" PSL (8' Long)	5	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
52	5-1/4"x11-7/8" PSL (12' Long)	1	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
53	5-1/4"x11-7/8" PSL (24' Long)	1	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
54	5-1/4"x11-7/8" PSL (6' Long)	2	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
55	5-1/4"x11-7/8" PSL (16' Long)	1	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
56	7"x11-7/8" PSL (20' Long)	1	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
57	7"x11-7/8" PSL (12' Long)	6	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
58	7"x11-7/8" PSL (14' Long)	1	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
59	5-1/2"x6" GL (6' Long)	25	EA	\$ -	\$ -	\$ -	\$ -	\$ -	GL Beam/Header
	Sub Floor Framing/Decking @ 2nd Floor:								
60	2x6x16' #2 DFL	12	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Blocking/Bridging/Bracing
61	2x10x16' #2 DFL	2	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Blocking/Bridging/Bracing
62	2x4x16' #2 DFL	5	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Blocking/Bridging/Bracing
63	11-7/8" TJI 210 (16' Long)	18	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Blocking 4, 5/S6.05
64	1-3/4"x11-7/8" LSL (16' Long)	136	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Rim board 4, 7, 12/S6.05

SR #	DESCRIPTION	QTY	UNIT	LABOR UNIT COST	MATERIAL UNIT COST	TOTAL LABOR	TOTAL MATERIAL	TOTAL COST	REMARKS
65	4x6x12' #1 DFL	11	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Posts
66	6x8x12' #1 DFL	2	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Posts
67	4x4x12' #1 DFL	1	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Posts
68	6x6x12' #1 DFL	2	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Posts
69	6x8x22' #1 DFL	2	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Posts
70	11-7/8" TJI 210 (12' Long)	853	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Floor Joist @ 16" OC
71	11-7/8" TJI 210 (6' Long)	32	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Floor Joist @ 16" OC
72	11-7/8" TJI 210 (8' Long)	74	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Floor Joist @ 16" OC
73	11-7/8" TJI 210 (10' Long)	58	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Floor Joist @ 16" OC
74	11-7/8" TJI 210 (16' Long)	87	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Floor Joist @ 16" OC
75	11-7/8" TJI 210 (18' Long)	42	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Floor Joist @ 16" OC
76	11-7/8" TJI 210 (14' Long)	14	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Floor Joist @ 16" OC
77	3/4" T&G Plywood Floor Sheathing 4x8	584	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Floor Sheathing
78	29oz Adhesive	195	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Adhesive
	Exterior Wall Framing @ 2nd Floor: (866 LF)								
79	2x6x16' #2 DFL	60	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Bottom Plate
80	2x6x104-5/8" #2 DFL	716	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Wall Studs @ 16" O.C
81	2x6x104-5/8" #2 DFL	666	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Extra Wall Studs (Openings, Corner & Intersections)
82	2x6x16' #2 DFL	179	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Double Top Plate & Mid Span Blocking
83	15/32" CDX Plywood 4x8	302	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Exterior Wall Sheathing
84	10'x125' Tyvek	8	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Tyvek
85	2"x165' Tyvek Tape	16	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Tyvek Tape
	Unit Separation Wall Framing @ 2nd Floor: (753 LF)								
86	2x4x16' #2 DFL	52	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Bottom Plate
87	2x4x104-5/8" #2 DFL	696	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Wall Studs @ 16" O.C
88	2x4x104-5/8" #2 DFL	248	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Extra Wall Studs (Openings, Corner & Intersections)
89	2x4x16' #2 DFL	156	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Double Top Plate & Mid Span Blocking
90	15/32" CDX Plywood 4x8	76	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Shear Wall Sheathing
	Corridor Wall Framing @ 2nd Floor: (593 LF)								
91	2x6x16' #2 DFL	41	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Bottom Plate
92	2x6x104-5/8" #2 DFL	759	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Wall Studs @ 16" O.C
93	2x6x104-5/8" #2 DFL	385	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Extra Wall Studs (Openings, Corner & Intersections)
94	2x6x16' #2 DFL	123	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Double Top Plate & Mid Span Blocking
95	15/32" CDX Plywood 4x8	110	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Shear Wall Sheathing
	Interior Wall Framing @ 2nd Floor: (2182 LF)								
96	2x4x16' #2 DFL	137	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Bottom Plate
97	2x6x16' #2 DFL	14	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Bottom Plate

SR #	DESCRIPTION	QTY	UNIT	LABOR UNIT COST	MATERIAL UNIT COST	TOTAL LABOR	TOTAL MATERIAL	TOTAL COST	REMARKS
98	2x4x104-5/8" #2 DFL	1646	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Wall Studs @ 16" O.C
99	2x4x104-5/8" #2 DFL	1340	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Extra Wall Studs (Openings, Corner & Intersections)
100	2x6x104-5/8" #2 DFL	159	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Wall Studs @ 16" O.C
101	2x6x104-5/8" #2 DFL	52	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Extra Wall Studs (Openings, Corner & Intersections)
102	2x4x16' #2 DFL	411	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Double Top Plate & Mid Span Blocking
103	2x6x16' #2 DFL	40	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Double Top Plate & Mid Span Blocking
104	15/32" CDX Plywood 4x8	24	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Shear Wall Sheathing
	Exterior Headers/Beams @ 2nd Floor:								
105	2x8x16' #2 HF	58	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Headers/Beams @ Openings
106	4x8x16' #1 DFL	1	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Headers/Beams @ Openings
	Interior Headers/Beams @ 2nd Floor:								
107	2x8x16' #2 HF	72	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Headers/Beams @ Openings
108	3-1/2"x11-7/8" PSL (12' Long)	3	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
109	3-1/2"x11-7/8" PSL (10' Long)	1	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
110	3-1/2"x11-7/8" PSL (6' Long)	1	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
111	3-1/2"x11-7/8" PSL (8' Long)	4	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
112	3-1/2"x11-7/8" PSL (18' Long)	1	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
113	3-1/2"x11-7/8" PSL (10' Long)	2	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
114	5-1/4"x11-7/8" PSL (22' Long)	2	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
115	5-1/4"x11-7/8" PSL (10' Long)	1	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
116	5-1/4"x11-7/8" PSL (12' Long)	3	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
117	5-1/4"x11-7/8" PSL (24' Long)	2	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
118	5-1/2"x6" GL (8' Long)	26	EA	\$ -	\$ -	\$ -	\$ -	\$ -	GL Beam/Header
119	5-1/2"x19-1/2" GL (22' Long)	1	EA	\$ -	\$ -	\$ -	\$ -	\$ -	GL Beam/Header
	Sub Floor Framing/Decking @ 3rd Floor:								
120	2x4x16' #2 DFL	5	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Blocking/Bridging/Bracing
121	11-7/8" TJI 210 (16' Long)	23	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Blocking 12/S6.06
122	1-3/4"x11-7/8" LSL (16' Long)	153	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Rim board 4, 7, 12/S6.05
123	5-1/4"x11-7/8" LSL (16' Long)	4	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Rim board 12/S6.03
124	4x6x10' #1 DFL	19	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Posts
125	6x10x10' #1 DFL	10	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Posts
126	2x12x22' #2 HF	4	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Floor Joist @ 16" OC
127	2x12x20' #2 HF	10	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Floor Joist @ 16" OC
128	2x12x22' #2 HF	7	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Floor Joist @ 12" OC
129	2x12x24' #2 HF	2	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Floor Joist @ 12" OC
130	11-7/8" TJI 360 (22' Long)	36	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Floor Joist @ 16" OC
131	11-7/8" TJI 360 (24' Long)	2	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Floor Joist @ 16" OC
132	11-7/8" TJI 360 (14' Long)	2	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Floor Joist @ 16" OC
133	11-7/8" TJI 360 (6' Long)	2	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Floor Joist @ 16" OC
134	11-7/8" TJI 210 (10' Long)	50	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Floor Joist @ 16" OC

SR #	DESCRIPTION	QTY	UNIT	LABOR UNIT COST	MATERIAL UNIT COST	TOTAL LABOR	TOTAL MATERIAL	TOTAL COST	REMARKS
135	11-7/8" TJI 210 (8' Long)	32	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Floor Joist @ 16" OC
136	11-7/8" TJI 210 (16' Long)	120	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Floor Joist @ 16" OC
137	11-7/8" TJI 210 (12' Long)	801	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Floor Joist @ 16" OC
138	11-7/8" TJI 210 (14' Long)	43	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Floor Joist @ 16" OC
139	11-7/8" TJI 210 (6' Long)	9	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Floor Joist @ 16" OC
140	11-7/8" TJI 210 (18' Long)	45	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Floor Joist @ 16" OC
141	3/4" T&G Plywood Floor Sheathing 4x8	613	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Floor Sheathing
142	29oz Adhesive	205	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Adhesive
	Exterior Wall Framing @ 3rd Floor: (852 LF)								
143	2x6x16' #2 DFL	59	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Bottom Plate
144	2x6x104-5/8" #2 DFL	704	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Wall Studs @ 16" O.C
145	2x6x104-5/8" #2 DFL	660	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Extra Wall Studs (Openings, Corner & Intersections)
146	2x6x16' #2 DFL	176	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Double Top Plate & Mid Span Blocking
147	15/32" CDX Plywood 4x8	259	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Exterior Wall Sheathing
148	10'x125' Tyvek	7	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Tyvek
149	2"x165' Tyvek Tape	14	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Tyvek Tape
	Unit Separation Wall Framing @ 3rd Floor: (753 LF)								
150	2x4x16' #2 DFL	52	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Bottom Plate
151	2x4x104-5/8" #2 DFL	623	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Wall Studs @ 16" O.C
152	2x4x104-5/8" #2 DFL	248	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Extra Wall Studs (Openings, Corner & Intersections)
153	2x4x16' #2 DFL	156	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Double Top Plate & Mid Span Blocking
154	15/32" CDX Plywood 4x8	71	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Shear Wall Sheathing
	Corridor Wall Framing @ 3rd Floor: (593 LF)								
155	2x6x16' #2 DFL	41	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Bottom Plate
156	2x6x104-5/8" #2 DFL	491	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Wall Studs @ 16" O.C
157	2x6x104-5/8" #2 DFL	385	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Extra Wall Studs (Openings, Corner & Intersections)
158	2x6x16' #2 DFL	123	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Double Top Plate & Mid Span Blocking
159	15/32" CDX Plywood 4x8	98	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Shear Wall Sheathing
	Interior Wall Framing @ 3rd Floor: (2178 LF)								
160	2x4x16' #2 DFL	137	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Bottom Plate
161	2x6x16' #2 DFL	14	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Bottom Plate
162	2x4x104-5/8" #2 DFL	1643	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Wall Studs @ 16" O.C
163	2x4x104-5/8" #2 DFL	1334	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Extra Wall Studs (Openings, Corner & Intersections)
164	2x6x104-5/8" #2 DFL	159	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Wall Studs @ 16" O.C
165	2x6x104-5/8" #2 DFL	52	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Extra Wall Studs (Openings, Corner & Intersections)
166	2x4x16' #2 DFL	410	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Double Top Plate & Mid Span Blocking
167	2x6x16' #2 DFL	40	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Double Top Plate & Mid Span Blocking

SR #	DESCRIPTION	QTY	UNIT	LABOR UNIT COST	MATERIAL UNIT COST	TOTAL LABOR	TOTAL MATERIAL	TOTAL COST	REMARKS
168	15/32" CDX Plywood 4x8	21	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Shear Wall Sheathing
	Exterior Headers/Beams @ 3rd Floor:								
169	2x8x16' #2 HF	47	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Headers/Beams @ Openings
170	4x8x16' #1 DFL	1	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Headers/Beams @ Openings
171	3-1/2"x11-7/8" PSL (16' Long)	1	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
	Interior Headers/Beams @ 3rd Floor:								
172	2x8x16' #2 HF	73	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Headers/Beams @ Openings
173	4x12x16' #1 DFL	1	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Headers/Beams @ Openings
174	3-1/2"x11-7/8" PSL (18' Long)	1	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
175	3-1/2"x11-7/8" PSL (10' Long)	2	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
176	3-1/2"x11-7/8" PSL (6' Long)	4	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
177	3-1/2"x11-7/8" PSL (8' Long)	29	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
178	3-1/2"x11-7/8" PSL (12' Long)	7	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
179	5-1/4"x11-7/8" PSL (22' Long)	2	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
180	5-1/4"x11-7/8" PSL (10' Long)	3	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
181	5-1/4"x11-7/8" PSL (12' Long)	1	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
182	5-1/4"x11-7/8" PSL (8' Long)	2	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PSL Beam/Header
	Parapet Wall Framing: (1110 LF)								
183	2x6x16' #2 DFL	77	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Bottom Plate
184	2x6x104-5/8" #2 DFL	144	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Wall Studs @ 16" O.C
185	2x6x12' #2 DFL	352	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Wall Studs @ 16" O.C
186	2x6x16' #2 DFL	153	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Double Top Plate & Mid Span Blocking
187	15/32" CDX Plywood 4x8	216	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Shear Wall Sheathing
	Exterior Headers/Beams @ Roof:								
188	2x8x16' #2 HF	2	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Headers/Beams @ Openings
	Low Roof Framing/Decking:								
189	2x6x16' #2 DFL	1	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Blocking
190	2x10x16' #2 HF	24	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Blocking
191	2x10x22' #2 HF	9	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Rafters @ 16" O.C.
192	2x10x24' #2 HF	23	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Rafters @ 16" O.C.
193	2x10x14' #2 HF	52	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Rafters @ 16" O.C.
194	2x10x12' #2 HF	2	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Rafters @ 16" O.C.
195	2x10x18' #2 HF	14	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Rafters @ 16" O.C.
196	2x6x10' #2 HF	5	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Rafters @ 24" O.C.
197	1/2" Plywood Roof Sheathing 4x8	77	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Roof Sheathing (Assumed)
198	Ply Clips	308	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Roof Decking Accessories

SR #	DESCRIPTION	QTY	UNIT	LABOR UNIT COST	MATERIAL UNIT COST	TOTAL LABOR	TOTAL MATERIAL	TOTAL COST	REMARKS
	Roof Framing/Decking:								
199	4x6x10' #1 DFL	18	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Posts
200	2x4x16' #2 DFL	5	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Blocking/Bridging/Bracing
201	1-3/4"x11-7/8" LSL (16' Long)	83	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Rim board 6,12/S6.06
202	11-7/8" TJI 210 (16' Long)	61	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Blocking 12/S6.06
203	11-7/8" TJI 210 (12' Long)	538	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Rafters @ 24" O.C.
204	11-7/8" TJI 210 (8' Long)	22	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Rafters @ 24" O.C.
205	11-7/8" TJI 210 (10' Long)	34	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Rafters @ 24" O.C.
206	11-7/8" TJI 210 (16' Long)	79	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Rafters @ 24" O.C.
207	11-7/8" TJI 210 (6' Long)	10	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Rafters @ 24" O.C.
208	11-7/8" TJI 210 (18' Long)	29	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Rafters @ 24" O.C.
209	11-7/8" TJI 210 (14' Long)	23	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Rafters @ 24" O.C.
210	11-7/8" TJI 210 (12' Long)	1	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Joist @ 16" O.C.
211	11-7/8" TJI 210 (18' Long)	1	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Joist @ 16" O.C.
212	11-7/8" TJI 210 (22' Long)	1	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Joist @ 16" O.C.
213	11-7/8" TJI 210 (20' Long)	17	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Joist @ 16" O.C.
214	1/2" Plywood Roof Sheathing 4x8	575	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Roof Sheathing (Assumed)
215	3/4" T&G Plywood Floor Sheathing 4x8	18	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Floor Sheathing
216	29oz Adhesive	6	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Adhesive
217	Ply Clips	2300	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Roof Decking Accessories
	Upper Roof Framing/Decking:								
218	1-3/4"x11-7/8" LSL (16' Long)	11	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Rim board 6,12/S6.06
219	11-7/8" TJI 210 (16' Long)	6	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Blocking 12/S6.06
220	11-7/8" TJI 210 (10' Long)	4	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Rafters @ 24" O.C.
221	11-7/8" TJI 210 (14' Long)	12	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Rafters @ 24" O.C.
222	11-7/8" TJI 210 (12' Long)	11	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Rafters @ 24" O.C.
223	1/2" Plywood Roof Sheathing 4x8	22	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Roof Sheathing (Assumed)
224	Ply Clips	88	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Roof Decking Accessories
	Stair Framing:								
225	2x12x16' #2 DFL	20	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Stringers
226	6-27/32" Risers (4'-0" W)	102	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Risers
227	11" Treads (4'-0" W)	93	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Treads
228	2x12x6' #2 HF	35	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Landing Joists @ 16" O.C.
229	3/4" T&G Plywood Floor Sheathing 4x8	8	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Landing Sheathing
230	29oz Adhesive	2	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Adhesive
	Simpson Hardwares:								
231	Simpson H2.5	1113	EA	\$ -	\$ -	\$ -	\$ -	\$ -	See Plan
232	Simpson H8	705	EA	\$ -	\$ -	\$ -	\$ -	\$ -	See Plan
233	Simpson CS16 Strap Tie (150ft Coil)	3	EA	\$ -	\$ -	\$ -	\$ -	\$ -	See Plan
234	Simpson CMSTC16 Strap Tie (52ft Coil)	5	EA	\$ -	\$ -	\$ -	\$ -	\$ -	See Plan

SR #	DESCRIPTION	QTY	UNIT	LABOR UNIT COST	MATERIAL UNIT COST	TOTAL LABOR	TOTAL MATERIAL	TOTAL COST	REMARKS
235	Simpson CMSTC16 Strap Tie (52ft Coil)	2	EA	\$ -	\$ -	\$ -	\$ -	\$ -	See Plan
236	Simpson HHU410	254	EA	\$ -	\$ -	\$ -	\$ -	\$ -	See Plan
237	Simpson HGU5.50/10	104	EA	\$ -	\$ -	\$ -	\$ -	\$ -	See Plan
238	Simpson HGU7.25/10	16	EA	\$ -	\$ -	\$ -	\$ -	\$ -	See Plan
239	Simpson HWP5.62	204	EA	\$ -	\$ -	\$ -	\$ -	\$ -	See Plan
240	Simpson 11-7/8" I Joist Hanger	1881	EA	\$ -	\$ -	\$ -	\$ -	\$ -	See Plan
241	Simpson HUCQ8-2	36	EA	\$ -	\$ -	\$ -	\$ -	\$ -	See Plan
242	Simpson HUCQ	30	EA	\$ -	\$ -	\$ -	\$ -	\$ -	See Plan
243	Simpson A35	1084	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Shearwall Schedule
244	5/8" Dia Anchor Bolts	566	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Shearwall Schedule
245	Simpson Strong Tie Allowance:	1	LS	\$ -	\$ 15,000	\$ -	\$ 15,000	\$ 15,000	
	<i>Note: 10% Wastage is figured with all quantities.</i>								
						Total Labor	Total Material		
						\$ -	\$ 15,000		
Sub Total								\$ 15,000	
Total Lumber								\$ 15,000	

PROJECT ADDRESS	MUCKLESHOOT INDIAN TRIBE SUPPORTIVE HOUSING	Pricing cells	Email	support@aconengineering.com					
DUE DATE	38415 AUBURN ENUMCLAW RD SE 98092	Confirm pricing	PH #						
DATE ON PLANS	5/19/2025	Confirm inclusion in scope	Website	http://aconengineering.com/					
ADDENDUM UPDATE	11/27/2024								
REVISION #	Not Issued	MAINTENANCE BUILDING							
REVISION #	0								
Total Basebid	\$1,000								
SR #	DESCRIPTION	QTY	UNIT	LABOR UNIT COST	MATERIAL UNIT COST	TOTAL LABOR	TOTAL MATERIAL	TOTAL COST	REMARKS
	Exterior Wall Framing: (98 LF)								
1	2x6x16' #2 DFL pt	7	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Bottom Plate
2	2x6x104-5/8" #2 DFL	81	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Wall Studs @ 16" O.C
3	2x6x104-5/8" #2 DFL	63	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Extra Wall Studs (Openings, Corner & Intersections)
4	2x6x16' #2 DFL	21	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Double Top Plate & Mid Span Blocking
5	15/32" CDX Plywood 4x8	31	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Exterior Wall Sheathing
6	10'x125' Tyvek	1	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Tyvek
7	2"x165' Tyvek Tape	2	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Tyvek Tape
	Interior Wall Framing: (30 LF)								
8	2x6x16' #2 DFL pt	2	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Bottom Plate
9	2x6x104-5/8" #2 DFL	25	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Wall Studs @ 16" O.C
10	2x6x104-5/8" #2 DFL	3	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Extra Wall Studs (Openings, Corner & Intersections)
11	2x6x16' #2 DFL	6	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Double Top Plate & Mid Span Blocking
	Headers/Beams:								
12	2x8x16' #2 HF	3	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Headers/Beams @ Openings
13	6x8x16' #1 DFL	2	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Headers/Beams @ Openings
	Roof Framing/Decking:								
14	2x4x16' #2 DFL	9	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Blocking/Bridging/Bracing 3,8,11/S6.08
14	2x6x16' #2 DFL pt	5	EA	\$ -	\$ -	\$ -	\$ -	\$ -	PT plate 6,7/S6.08
15	2x6x16' #2 DFL	4	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Nailer/Blocking 4,12/S6.08
16	3x6x16' #2 DFL	10	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Fascia Board 6,7,8,11/S6.08
17	2x12x16' #2 DFL	3	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Blocking 11/S6.08
18	2x4x8' #2 HF	19	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Outriggers @ 24" O.C.
19	1/2" Plywood Roof Sheathing 4x8	50	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Roof Decking
20	Ply Clips	200	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Roof Decking Accessories
	Simpson Hardwares:								
21	Simpson H1A	42	EA	\$ -	\$ -	\$ -	\$ -	\$ -	11/S6.08
22	Simpson A34	21	EA	\$ -	\$ -	\$ -	\$ -	\$ -	8/S6.08
23	Simpson A35	29	EA	\$ -	\$ -	\$ -	\$ -	\$ -	7/S6.08
24	5/8" Dia Anchor Bolts	34	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Shearwall Schedule & 6,7/S6.08

SR #	DESCRIPTION	QTY	UNIT	LABOR UNIT COST	MATERIAL UNIT COST	TOTAL LABOR	TOTAL MATERIAL	TOTAL COST	REMARKS
25	Simpson Strong Tie Allowance:	1	LS	\$ -	\$ 1,000	\$ -	\$ 1,000	\$ 1,000	
	<i>Note: 10% Wastage is figured with all quantities.</i>								
						Total Labor	Total Material		
						\$ -	\$ 1,000		
Sub Total								\$ 1,000	
Total Lumber								\$ 1,000	

PROJECT	MUCKLESHOOT INDIAN TRIBE SUPPORTIVE HOUSING	Pricing cells	Email	support@aconengineering.com						
ADDRESS	38415 AUBURN ENUMCLAW RD SE 98092	Confirm pricing	PH #							
DUE DATE	5/19/2025	Confirm inclusion in scope	Website	http://aconengineering.com/						
DATE ON PLANS	11/27/2024									
ADDENDUM UPDATE	Not Issued	SHELTER								
REVISION #	0									
Total Basebid	\$300									
SR #	DESCRIPTION	QTY	UNIT	LABOR UNIT COST	MATERIAL UNIT COST	TOTAL LABOR	TOTAL MATERIAL	TOTAL COST	REMARKS	
	Shelter Framing/Decking:									
1	2x10x16' #2 DFL	3	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Blocking/Bridging/Bracing 2/S6.02	
2	2x4x16' #2 DFL	3	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Nailer 2/S6.02	
3	2x10x14' #2 HF	22	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Rafters @ 16" O.C.	
4	1/2" Plywood Roof Sheathing 4x8	13	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Roof Decking	
5	Ply Clips	52	EA	\$ -	\$ -	\$ -	\$ -	\$ -	Roof Decking Accessories	
	Simpson Hardwares:									
6	Simpson A35	20	EA	\$ -	\$ -	\$ -	\$ -	\$ -	2/S6.02	
7	5/8" Dia W.T.S @ 48" O.C	10	EA	\$ -	\$ -	\$ -	\$ -	\$ -	2/S6.02	
8	Simpson Strong Tie Allowance:	1	LS	\$ -	\$ 300	\$ -	\$ 300	\$ 300		
	Note: 10% Wastage is figured with all quantities.									
						Total Labor	Total Material			
						\$ -	\$ 300			
Sub Total								\$ 300		
Total Lumber								\$ 300		

PROJECT ADDRESS	MUCKLESHOOT INDIAN TRIBE SUPPORTIVE HOUSING 38415 AUBURN ENUMCLAW RD SE 98092		
SR #	DESCRIPTION	QTY	UNIT
	<u>Consolidated List:</u>		
1	1/2" Plywood Roof Sheathing 4x8	674	EA
2	10'x125' Tyvek	24	EA
3	11" Treads (4'-0" W)	93	EA
4	11-7/8" TJI 210 (10' Long)	146	EA
5	11-7/8" TJI 210 (12' Long)	2204	EA
6	11-7/8" TJI 210 (14' Long)	92	EA
7	11-7/8" TJI 210 (16' Long)	394	EA
8	11-7/8" TJI 210 (18' Long)	117	EA
9	11-7/8" TJI 210 (20' Long)	17	EA
10	11-7/8" TJI 210 (22' Long)	1	EA
11	11-7/8" TJI 210 (6' Long)	51	EA
12	11-7/8" TJI 210 (8' Long)	128	EA
13	11-7/8" TJI 360 (14' Long)	2	EA
14	11-7/8" TJI 360 (22' Long)	36	EA
15	11-7/8" TJI 360 (24' Long)	2	EA
16	11-7/8" TJI 360 (6' Long)	2	EA
17	1-3/4"x11-7/8" LSL (16' Long)	383	EA

ADDRESS 38415 AUBURN ENUMCLAW RD SE 98092

SR #	DESCRIPTION	QTY	UNIT
18	15/32" CDX Plywood 4x8	1750	EA
19	2"x165' Tyvek Tape	48	EA
20	29oz Adhesive	408	EA
21	2x10x12' #2 HF	2	EA
22	2x10x14' #2 HF	52	EA
23	2x10x16' #2 DFL	2	EA
24	2x10x16' #2 HF	24	EA
25	2x10x18' #2 HF	14	EA
26	2x10x22' #2 HF	9	EA
27	2x10x24' #2 HF	23	EA
28	2x12x16' #2 DFL	20	EA
29	2x12x20' #2 HF	10	EA
30	2x12x22' #2 HF	11	EA
31	2x12x24' #2 HF	2	EA
32	2x12x6' #2 HF	35	EA
33	2x4x104-5/8" #2 DFL	7778	EA
34	2x4x12' #2 DFL	3205	EA
35	2x4x16' #2 DFL	1980	EA
36	2x4x16' #2 DFL pt	153	EA
37	2x6x10' #2 HF	5	EA
38	2x6x104-5/8" #2 DFL	5332	EA
39	2x6x12' #2 DFL	2950	EA

ADDRESS 38415 AUBURN ENUMCLAW RD SE 98092

SR #	DESCRIPTION	QTY	UNIT
40	2x6x16' #2 DFL	1476	EA
41	2x6x16' #2 DFL pt	109	EA
42	2x8x16' #2 HF	347	EA
43	3/4" T&G Plywood Floor Sheathing 4x8	1223	EA
44	3-1/2"x11-7/8" PSL (10' Long)	35	EA
45	3-1/2"x11-7/8" PSL (12' Long)	39	EA
46	3-1/2"x11-7/8" PSL (16' Long)	2	EA
47	3-1/2"x11-7/8" PSL (18' Long)	2	EA
48	3-1/2"x11-7/8" PSL (22' Long)	1	EA
49	3-1/2"x11-7/8" PSL (28' Long)	1	EA
50	3-1/2"x11-7/8" PSL (6' Long)	41	EA
51	3-1/2"x11-7/8" PSL (8' Long)	41	EA
52	3x4x16' #2 DFL pt	2	EA
53	4x12x16' #1 DFL	1	EA
54	4x4x12' #1 DFL	1	EA
55	4x6x10' #1 DFL	37	EA
56	4x6x12' #1 DFL	11	EA
57	4x8x16' #1 DFL	2	EA
58	5-1/2"x18" GL (14' Long)	2	EA
59	5-1/2"x18" GL (8' Long)	3	EA
60	5-1/2"x19-1/2" GL (22' Long)	1	EA
61	5-1/2"x6" GL (6' Long)	25	EA

ADDRESS 38415 AUBURN ENUMCLAW RD SE 98092

SR #	DESCRIPTION	QTY	UNIT
62	5-1/2"x6" GL (8' Long)	26	EA
63	5-1/4"x11-7/8" LSL (16' Long)	4	EA
64	5-1/4"x11-7/8" PSL (10' Long)	10	EA
65	5-1/4"x11-7/8" PSL (12' Long)	5	EA
66	5-1/4"x11-7/8" PSL (16' Long)	1	EA
67	5-1/4"x11-7/8" PSL (22' Long)	6	EA
68	5-1/4"x11-7/8" PSL (24' Long)	3	EA
69	5-1/4"x11-7/8" PSL (26' Long)	2	EA
70	5-1/4"x11-7/8" PSL (6' Long)	2	EA
71	5-1/4"x11-7/8" PSL (8' Long)	7	EA
72	6-27/32" Risers (4'-0" W)	102	EA
73	6x10x10' #1 DFL	10	EA
74	6x12x16' #1 DFL	3	EA
75	6x6x12' #1 DFL	2	EA
76	6x8x12' #1 DFL	2	EA
77	6x8x22' #1 DFL	2	EA
78	7"x11-7/8" PSL (12' Long)	6	EA
79	7"x11-7/8" PSL (14' Long)	1	EA
80	7"x11-7/8" PSL (20' Long)	1	EA
81	Ply Clips	2696	EA
	<u>Simpson Hardwares:</u>		

ADDRESS | **38415 AUBURN ENUMCLAW RD SE 98092**

SR #	DESCRIPTION	QTY	UNIT
82	Simpson H2.5	1113	EA
83	Simpson H8	705	EA
84	Simpson CS16 Strap Tie (150ft Coil)	3	EA
85	Simpson CMSTC16 Strap Tie (52ft Coil)	7	EA
86	Simpson HHU410	254	EA
87	Simpson HGU5.50/10	104	EA
88	Simpson HGU7.25/10	16	EA
89	Simpson HWP5.62	204	EA
90	Simpson 11-7/8" I Joist Hanger	1881	EA
91	Simpson HUCQ8-2	36	EA
92	Simpson HUCQ	30	EA
93	Simpson A35	1084	EA
94	5/8" Dia Anchor Bolts	566	EA
95	Simpson Strong Tie Allowance: (\$ 6,000)	1	LS
	<i>Note: 10% Wastage is figured with all</i>		

PROJECT ADDRESS	MUCKLESHOOT INDIAN TRIBE SUPPORTIVE HOUSING 38415 AUBURN ENUMCLAW RD SE 98092		
SR #	DESCRIPTION	QTY	UNIT
	<u>Consolidated List:</u>		
1	1/2" Plywood Roof Sheathing 4x8	50	EA
2	10'x125' Tyvek	1	EA
3	15/32" CDX Plywood 4x8	31	EA
4	2"x165' Tyvek Tape	2	EA
5	2x12x16' #2 DFL	3	EA
6	2x4x16' #2 DFL	9	EA
7	2x4x8' #2 HF	19	EA
8	2x6x104-5/8" #2 DFL	172	EA
9	2x6x16' #2 DFL	31	EA
10	2x6x16' #2 DFL pt	14	EA
11	2x8x16' #2 HF	3	EA
12	3x6x16' #2 DFL	10	EA
13	6x8x16' #1 DFL	2	EA
14	Ply Clips	200	EA
	<u>Simpson Hardwares:</u>		

ADDRESS | **38415 AUBURN ENUMCLAW RD SE 98092**

SR #	DESCRIPTION	QTY	UNIT
15	Simpson A34	21	EA
16	Simpson A35	29	EA
17	Simpson H1A	42	EA
18	5/8" Dia Anchor Bolts	34	EA
19	Simpson Strong Tie Allowance: (\$ 1,000)	1	LS
	<i>Note: 10% Wastage is figured with all</i>		

PROJECT ADDRESS	MUCKLESHOOT INDIAN TRIBE SUPPORTIVE HOUSING 38415 AUBURN ENUMCLAW RD SE 98092		
SR #	DESCRIPTION	QTY	UNIT
	<u>Consolidated List:</u>		
1	2x10x16' #2 DFL	3	EA
2	2x4x16' #2 DFL	3	EA
3	2x10x14' #2 HF	22	EA
4	1/2" Plywood Roof Sheathing 4x8	13	EA
5	Ply Clips	52	EA
	<u>Simpson Hardwares:</u>		
6	Simpson A35	20	EA
7	5/8" Dia W.T.S @ 48" O.C	10	EA
8	<u>Simpson Strong Tie Allowance: (\$ 300)</u>	1	LS
	<i>Note: 10% Wastage is figured with all</i>		

PROJECT ADDRESS	MUCKLESHOOT INDIAN TRIBE SUPPORTIVE HOUSING 38415 AUBURN ENUMCLAW RD SE 98092					MASTER SUMMARY FOR ALL STRUCTURERS					
SR #	DESCRIPTION	UNIT	BLOCK 2	BLOCK 3	BLOCK 4	TOTAL QTY	LABOR UNIT COST	MATERIAL UNIT COST	TOTAL LABOR	TOTAL MATERIAL	TOTAL COST
			1 EA	1 EA	1 EA						
1	1/2" Plywood Roof Sheathing 4x8	EA	674	50	13	737	\$ -	\$ -	\$ -	\$ -	\$ -
2	10'x125' Tyvek	EA	24	1	0	25	\$ -	\$ -	\$ -	\$ -	\$ -
3	11" Treads (4'-0" W)	EA	93	0	0	93	\$ -	\$ -	\$ -	\$ -	\$ -
4	11-7/8" TJI 210 (10' Long)	EA	146	0	0	146	\$ -	\$ -	\$ -	\$ -	\$ -
5	11-7/8" TJI 210 (12' Long)	EA	2204	0	0	2204	\$ -	\$ -	\$ -	\$ -	\$ -
6	11-7/8" TJI 210 (14' Long)	EA	92	0	0	92	\$ -	\$ -	\$ -	\$ -	\$ -
7	11-7/8" TJI 210 (16' Long)	EA	394	0	0	394	\$ -	\$ -	\$ -	\$ -	\$ -
8	11-7/8" TJI 210 (18' Long)	EA	117	0	0	117	\$ -	\$ -	\$ -	\$ -	\$ -
9	11-7/8" TJI 210 (20' Long)	EA	17	0	0	17	\$ -	\$ -	\$ -	\$ -	\$ -
10	11-7/8" TJI 210 (22' Long)	EA	1	0	0	1	\$ -	\$ -	\$ -	\$ -	\$ -
11	11-7/8" TJI 210 (6' Long)	EA	51	0	0	51	\$ -	\$ -	\$ -	\$ -	\$ -
12	11-7/8" TJI 210 (8' Long)	EA	128	0	0	128	\$ -	\$ -	\$ -	\$ -	\$ -
13	11-7/8" TJI 360 (14' Long)	EA	2	0	0	2	\$ -	\$ -	\$ -	\$ -	\$ -
14	11-7/8" TJI 360 (22' Long)	EA	36	0	0	36	\$ -	\$ -	\$ -	\$ -	\$ -
15	11-7/8" TJI 360 (24' Long)	EA	2	0	0	2	\$ -	\$ -	\$ -	\$ -	\$ -
16	11-7/8" TJI 360 (6' Long)	EA	2	0	0	2	\$ -	\$ -	\$ -	\$ -	\$ -
17	1-3/4"x11-7/8" LSL (16' Long)	EA	383	0	0	383	\$ -	\$ -	\$ -	\$ -	\$ -
18	15/32" CDX Plywood 4x8	EA	1750	31	0	1781	\$ -	\$ -	\$ -	\$ -	\$ -
19	2"x165' Tyvek Tape	EA	48	2	0	50	\$ -	\$ -	\$ -	\$ -	\$ -
20	29oz Adhesive	EA	408	0	0	408	\$ -	\$ -	\$ -	\$ -	\$ -
21	2x10x12' #2 HF	EA	2	0	0	2	\$ -	\$ -	\$ -	\$ -	\$ -
22	2x10x14' #2 HF	EA	52	0	22	74	\$ -	\$ -	\$ -	\$ -	\$ -
23	2x10x16' #2 DFL	EA	2	0	3	5	\$ -	\$ -	\$ -	\$ -	\$ -
24	2x10x16' #2 HF	EA	24	0	0	24	\$ -	\$ -	\$ -	\$ -	\$ -
25	2x10x18' #2 HF	EA	14	0	0	14	\$ -	\$ -	\$ -	\$ -	\$ -
26	2x10x22' #2 HF	EA	9	0	0	9	\$ -	\$ -	\$ -	\$ -	\$ -
27	2x10x24' #2 HF	EA	23	0	0	23	\$ -	\$ -	\$ -	\$ -	\$ -
28	2x12x16' #2 DFL	EA	20	3	0	23	\$ -	\$ -	\$ -	\$ -	\$ -
29	2x12x20' #2 HF	EA	10	0	0	10	\$ -	\$ -	\$ -	\$ -	\$ -
30	2x12x22' #2 HF	EA	11	0	0	11	\$ -	\$ -	\$ -	\$ -	\$ -
31	2x12x24' #2 HF	EA	2	0	0	2	\$ -	\$ -	\$ -	\$ -	\$ -
32	2x12x6' #2 HF	EA	35	0	0	35	\$ -	\$ -	\$ -	\$ -	\$ -
33	2x4x104-5/8" #2 DFL	EA	7778	0	0	7778	\$ -	\$ -	\$ -	\$ -	\$ -
34	2x4x12' #2 DFL	EA	3205	0	0	3205	\$ -	\$ -	\$ -	\$ -	\$ -
35	2x4x16' #2 DFL	EA	1980	9	3	1992	\$ -	\$ -	\$ -	\$ -	\$ -
36	2x4x16' #2 DFL pt	EA	153	0	0	153	\$ -	\$ -	\$ -	\$ -	\$ -
37	2x6x10' #2 HF	EA	5	0	0	5	\$ -	\$ -	\$ -	\$ -	\$ -
38	2x6x104-5/8" #2 DFL	EA	5332	172	0	5504	\$ -	\$ -	\$ -	\$ -	\$ -
39	2x6x12' #2 DFL	EA	2950	0	0	2950	\$ -	\$ -	\$ -	\$ -	\$ -
40	2x6x16' #2 DFL	EA	1476	31	0	1507	\$ -	\$ -	\$ -	\$ -	\$ -
41	2x6x16' #2 DFL pt	EA	109	14	0	123	\$ -	\$ -	\$ -	\$ -	\$ -
42	2x8x16' #2 HF	EA	347	3	0	350	\$ -	\$ -	\$ -	\$ -	\$ -
43	3/4" T&G Plywood Floor Sheathing 4x8	EA	1223	0	0	1223	\$ -	\$ -	\$ -	\$ -	\$ -
44	3-1/2"x11-7/8" PSL (10' Long)	EA	35	0	0	35	\$ -	\$ -	\$ -	\$ -	\$ -
45	3-1/2"x11-7/8" PSL (12' Long)	EA	39	0	0	39	\$ -	\$ -	\$ -	\$ -	\$ -
46	3-1/2"x11-7/8" PSL (16' Long)	EA	2	0	0	2	\$ -	\$ -	\$ -	\$ -	\$ -
47	3-1/2"x11-7/8" PSL (18' Long)	EA	2	0	0	2	\$ -	\$ -	\$ -	\$ -	\$ -

PROJECT ADDRESS	MUCKLESHOOT INDIAN TRIBE SUPPORTIVE HOUSING 38415 AUBURN ENUMCLAW RD SE 98092						MASTER SUMMARY FOR ALL STRUCTURERS				
SR #	DESCRIPTION	UNIT	BLOCK 2	BLOCK 3	BLOCK 4	TOTAL QTY	LABOR UNIT COST	MATERIAL UNIT COST	TOTAL LABOR	TOTAL MATERIAL	TOTAL COST
48	3-1/2"x11-7/8" PSL (22' Long)	EA	1	0	0	1	\$ -	\$ -	\$ -	\$ -	\$ -
49	3-1/2"x11-7/8" PSL (28' Long)	EA	1	0	0	1	\$ -	\$ -	\$ -	\$ -	\$ -
50	3-1/2"x11-7/8" PSL (6' Long)	EA	41	0	0	41	\$ -	\$ -	\$ -	\$ -	\$ -
51	3-1/2"x11-7/8" PSL (8' Long)	EA	41	0	0	41	\$ -	\$ -	\$ -	\$ -	\$ -
52	3x4x16' #2 DFL pt	EA	2	0	0	2	\$ -	\$ -	\$ -	\$ -	\$ -
53	4x12x16' #1 DFL	EA	1	0	0	1	\$ -	\$ -	\$ -	\$ -	\$ -
54	4x4x12' #1 DFL	EA	1	0	0	1	\$ -	\$ -	\$ -	\$ -	\$ -
55	4x6x10' #1 DFL	EA	37	0	0	37	\$ -	\$ -	\$ -	\$ -	\$ -
56	4x6x12' #1 DFL	EA	11	0	0	11	\$ -	\$ -	\$ -	\$ -	\$ -
57	4x8x16' #1 DFL	EA	2	0	0	2	\$ -	\$ -	\$ -	\$ -	\$ -
58	5-1/2"x18" GL (14' Long)	EA	2	0	0	2	\$ -	\$ -	\$ -	\$ -	\$ -
59	5-1/2"x18" GL (8' Long)	EA	3	0	0	3	\$ -	\$ -	\$ -	\$ -	\$ -
60	5-1/2"x19-1/2" GL (22' Long)	EA	1	0	0	1	\$ -	\$ -	\$ -	\$ -	\$ -
61	5-1/2"x6" GL (6' Long)	EA	25	0	0	25	\$ -	\$ -	\$ -	\$ -	\$ -
62	5-1/2"x6" GL (8' Long)	EA	26	0	0	26	\$ -	\$ -	\$ -	\$ -	\$ -
63	5-1/4"x11-7/8" LSL (16' Long)	EA	4	0	0	4	\$ -	\$ -	\$ -	\$ -	\$ -
64	5-1/4"x11-7/8" PSL (10' Long)	EA	10	0	0	10	\$ -	\$ -	\$ -	\$ -	\$ -
65	5-1/4"x11-7/8" PSL (12' Long)	EA	5	0	0	5	\$ -	\$ -	\$ -	\$ -	\$ -
66	5-1/4"x11-7/8" PSL (16' Long)	EA	1	0	0	1	\$ -	\$ -	\$ -	\$ -	\$ -
67	5-1/4"x11-7/8" PSL (22' Long)	EA	6	0	0	6	\$ -	\$ -	\$ -	\$ -	\$ -
68	5-1/4"x11-7/8" PSL (24' Long)	EA	3	0	0	3	\$ -	\$ -	\$ -	\$ -	\$ -
69	5-1/4"x11-7/8" PSL (26' Long)	EA	2	0	0	2	\$ -	\$ -	\$ -	\$ -	\$ -
70	5-1/4"x11-7/8" PSL (6' Long)	EA	2	0	0	2	\$ -	\$ -	\$ -	\$ -	\$ -
71	5-1/4"x11-7/8" PSL (8' Long)	EA	7	0	0	7	\$ -	\$ -	\$ -	\$ -	\$ -
72	6-27/32" Risers (4'-0" W)	EA	102	0	0	102	\$ -	\$ -	\$ -	\$ -	\$ -
73	6x10x10' #1 DFL	EA	10	0	0	10	\$ -	\$ -	\$ -	\$ -	\$ -
74	6x12x16' #1 DFL	EA	3	0	0	3	\$ -	\$ -	\$ -	\$ -	\$ -
75	6x6x12' #1 DFL	EA	2	0	0	2	\$ -	\$ -	\$ -	\$ -	\$ -
76	6x8x12' #1 DFL	EA	2	0	0	2	\$ -	\$ -	\$ -	\$ -	\$ -
77	6x8x22' #1 DFL	EA	2	0	0	2	\$ -	\$ -	\$ -	\$ -	\$ -
78	7"x11-7/8" PSL (12' Long)	EA	6	0	0	6	\$ -	\$ -	\$ -	\$ -	\$ -
79	7"x11-7/8" PSL (14' Long)	EA	1	0	0	1	\$ -	\$ -	\$ -	\$ -	\$ -
80	7"x11-7/8" PSL (20' Long)	EA	1	0	0	1	\$ -	\$ -	\$ -	\$ -	\$ -
81	Ply Clips	EA	2696	200	52	2948	\$ -	\$ -	\$ -	\$ -	\$ -
82	Simpson H2.5	EA	1113	0	0	1113	\$ -	\$ -	\$ -	\$ -	\$ -
83	Simpson H8	EA	705	0	0	705	\$ -	\$ -	\$ -	\$ -	\$ -
84	Simpson CS16 Strap Tie (150ft Coil)	EA	3	0	0	3	\$ -	\$ -	\$ -	\$ -	\$ -
85	Simpson CMSTC16 Strap Tie (52ft Coil)	EA	7	0	0	7	\$ -	\$ -	\$ -	\$ -	\$ -
86	Simpson HHU410	EA	254	0	0	254	\$ -	\$ -	\$ -	\$ -	\$ -
87	Simpson HGU5.50/10	EA	104	0	0	104	\$ -	\$ -	\$ -	\$ -	\$ -
88	Simpson HGU7.25/10	EA	16	0	0	16	\$ -	\$ -	\$ -	\$ -	\$ -
89	Simpson HWP5.62	EA	204	0	0	204	\$ -	\$ -	\$ -	\$ -	\$ -
90	Simpson 11-7/8" I Joist Hanger	EA	1881	0	0	1881	\$ -	\$ -	\$ -	\$ -	\$ -
91	Simpson HUCQ8-2	EA	36	0	0	36	\$ -	\$ -	\$ -	\$ -	\$ -
92	Simpson HUCQ	EA	30	0	0	30	\$ -	\$ -	\$ -	\$ -	\$ -
93	Simpson A35	EA	1084	29	20	1133	\$ -	\$ -	\$ -	\$ -	\$ -
94	5/8" Dia Anchor Bolts	EA	566	34	0	600	\$ -	\$ -	\$ -	\$ -	\$ -
95	2x4x8' #2 HF	EA	0	19	0	19	\$ -	\$ -	\$ -	\$ -	\$ -

PROJECT		MUCKLESHOOT INDIAN TRIBE SUPPORTIVE HOUSING					MASTER SUMMARY FOR ALL STRUCTURERS				
ADDRESS		38415 AUBURN ENUMCLAW RD SE 98092									
SR #	DESCRIPTION	UNIT	BLOCK 2	BLOCK 3	BLOCK 4	TOTAL QTY	LABOR UNIT COST	MATERIAL UNIT COST	TOTAL LABOR	TOTAL MATERIAL	TOTAL COST
96	3x6x16' #2 DFL	EA	0	10	0	10	\$ -	\$ -	\$ -	\$ -	\$ -
97	6x8x16' #1 DFL	EA	0	2	0	2	\$ -	\$ -	\$ -	\$ -	\$ -
98	Simpson A34	EA	0	21	0	21	\$ -	\$ -	\$ -	\$ -	\$ -
99	Simpson H1A	EA	0	42	0	42	\$ -	\$ -	\$ -	\$ -	\$ -
100	5/8" Dia W.T.S @ 48" O.C	EA	0	0	10	10	\$ -	\$ -	\$ -	\$ -	\$ -
101	Simpson Strong Tie Allowance:	LS	1	1	1	1	\$ -	\$ 16,300.00	\$ -	\$ 16,300.00	\$ 16,300.00
									Total Labor	Total Material	
									\$ -	\$ 16,300	
							Sub Total				\$ 16,300
							Total Lumber				\$ 16,300

1/2" Plywood Roof Sheathing 4x8
10'x125' Tyvek
11" Treads (4'-0" W)
11-7/8" TJI 210 (10' Long)
11-7/8" TJI 210 (12' Long)
11-7/8" TJI 210 (14' Long)
11-7/8" TJI 210 (16' Long)
11-7/8" TJI 210 (18' Long)
11-7/8" TJI 210 (20' Long)
11-7/8" TJI 210 (22' Long)
11-7/8" TJI 210 (6' Long)
11-7/8" TJI 210 (8' Long)
11-7/8" TJI 360 (14' Long)
11-7/8" TJI 360 (22' Long)
11-7/8" TJI 360 (24' Long)
11-7/8" TJI 360 (6' Long)
1-3/4"x11-7/8" LSL (16' Long)
15/32" CDX Plywood 4x8
2"x165' Tyvek Tape
29oz Adhesive
2x10x12' #2 HF
2x10x14' #2 HF
2x10x16' #2 DFL
2x10x16' #2 HF
2x10x18' #2 HF
2x10x22' #2 HF
2x10x24' #2 HF
2x12x16' #2 DFL
2x12x20' #2 HF
2x12x22' #2 HF
2x12x24' #2 HF
2x12x6' #2 HF
2x4x104-5/8" #2 DFL
2x4x12' #2 DFL
2x4x16' #2 DFL
2x4x16' #2 DFL pt
2x6x10' #2 HF
2x6x104-5/8" #2 DFL
2x6x12' #2 DFL
2x6x16' #2 DFL
2x6x16' #2 DFL pt
2x8x16' #2 HF
3/4" T&G Plywood Floor Sheathing 4x8
3-1/2"x11-7/8" PSL (10' Long)
3-1/2"x11-7/8" PSL (12' Long)

3-1/2"x11-7/8" PSL (16' Long)
3-1/2"x11-7/8" PSL (18' Long)
3-1/2"x11-7/8" PSL (22' Long)
3-1/2"x11-7/8" PSL (28' Long)
3-1/2"x11-7/8" PSL (6' Long)
3-1/2"x11-7/8" PSL (8' Long)
3x4x16' #2 DFL pt
4x12x16' #1 DFL
4x4x12' #1 DFL
4x6x10' #1 DFL
4x6x12' #1 DFL
4x8x16' #1 DFL
5-1/2"x18" GL (14' Long)
5-1/2"x18" GL (8' Long)
5-1/2"x19-1/2" GL (22' Long)
5-1/2"x6" GL (6' Long)
5-1/2"x6" GL (8' Long)
5-1/4"x11-7/8" LSL (16' Long)
5-1/4"x11-7/8" PSL (10' Long)
5-1/4"x11-7/8" PSL (12' Long)
5-1/4"x11-7/8" PSL (16' Long)
5-1/4"x11-7/8" PSL (22' Long)
5-1/4"x11-7/8" PSL (24' Long)
5-1/4"x11-7/8" PSL (26' Long)
5-1/4"x11-7/8" PSL (6' Long)
5-1/4"x11-7/8" PSL (8' Long)
6-27/32" Risers (4'-0" W)
6x10x10' #1 DFL
6x12x16' #1 DFL
6x6x12' #1 DFL
6x8x12' #1 DFL
6x8x22' #1 DFL
7"x11-7/8" PSL (12' Long)
7"x11-7/8" PSL (14' Long)
7"x11-7/8" PSL (20' Long)
Ply Clips
Simpson H2.5
Simpson H8
Simpson CS16 Strap Tie (150ft Coil)
Simpson CMSTC16 Strap Tie (52ft Coil)
Simpson HHU410
Simpson HGU5.50/10
Simpson HGU7.25/10
Simpson HWP5.62
Simpson 11-7/8" I Joist Hanger
Simpson HUCQ8-2

Simpson HUCQ
Simpson A35
5/8" Dia Anchor Bolts
1/2" Plywood Roof Sheathing 4x8
2x4x8' #2 HF
3x6x16' #2 DFL
6x8x16' #1 DFL
Simpson A34
Simpson H1A
5/8" Dia W.T.S @ 48" O.C